

Installing the Serial-to-COM Adapter

This section will show you how to connect a Scale Cable Adapter to the COM Port on your Terminal.

Introduction

Each Frozen Yogurt, Grocery, or other weight based client requires one (1) COM Adapter for the use of a scale, or other weight device, per device.

Note:

The Terminal should be laying face down on a flat, soft surface exposing the connectable ports.

Getting Started

Before attaching the COM Adapter to the Terminal, make sure it is labeled "Scale".



Policy is to include an extra adapter per each Terminal and visibly label each one "Scale".

Step 1

With the clip facing up, plug the COM Adapter into **COM1 port**.



Complete

This is how the Terminal should look when the COM Adapter is attached.

